BUHVEY & REMONUMENTATION

APR 2 9 1996

JUDITH D. ROEHM Ontonason County 09/25/95

14:49

49 9,00

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Page 1 of 1

For corners in

_0	ntonagon (County)	Located In:	Corner Code ##	
1.	Public Land Survey	T 49N R 42W • T R	I-2	
		T R T R		
2.	Property Controlling	S T R		
3.	in Section Miscellaneous Property in Sec.	S T R S T R S T R		Register of Deeds Stamp & File Number

4. Lot No. ______, Recorded Plat __

5. Private Claims ___

1/4 Corner 2 & 3; T.49 N., R.42 W.

Richard L. Drahn in a field survey on August 21, 19 95 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

A B C D E F G H J K L M

2
6 5 4 3 9 10 11 12
5
6 18 17 16 15 14 13
7
8 19 20 21 22 23 24
9
10 30 29 28 27 26 25
11
12 31 32 33 34 35 36

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by William Burt on June 7, 1848. Original B.T.s

--- Lynn 14" S.61 W., 24 links (15.84') --- Hemlock 20" N.80½ E., 8 links (5.28').

Corner restored by Richard L. Drahn, R.L.S. 21564 on8/29/77 from the remains of the original Hemlock B.T. and from natural feature ties and distances to recovered corners north and south. He set a 2" by 5' galvanized iron pipe with a 3" stamped brass cap and the following new B.T.s: --- 5" (6") Sugar Maple N.18 E. (N.20 E.) 48.1' (48.11') --- 8" Sugar Maple (9") S.78E. (S.76 E) 27.4' (27.43') --- 5" (6") Sugar Maple S.81 W. (S.82 W.) 50.6' (50.77')

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 7' Metal sign post S.07 W. (S.12 W.) 1.8' (1.94'). Corner recorded in Ontonagon County; Liber 1, Page 167 on 4/25/79.

Recovered monument as described and bearing trees as shown in parentheses above. No hemlock wood or bark remains in the stump hole of the GLO B.T.

Ace 74 research form on file with Ontonagon County Records.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

New bearing tree established:

3.12'

6" Basswood

S.16 E.

--- anotin appoored

Date ...

COUNTY REPRESENTATIVE

RICHARD
L. DRAHN
LAND
SURVEYOR
No.
21564

signed by Richard L. Dralin

September 10, 1995

Surveyor's Michigan License No. 21564

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

9-20-95