

DEC 1 6 1996

JUDITH D. ROEHM Ontonason County 07/11/96 ΩS: 54

4/ 111 JEM Fee:

1

9.00 Page

LC COMMISSION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Ontonagon Located In:

T 49NR 43W K-12 _ R _

Corner Code ##

R R

R 2. Property Controlling Т _ A _ in Section 3. Miscellaneous R. S T Property in Sec.

Register of Deeds Stamp & File Number

____ , Recorded Plat _

5. Private Claims _

1. Public Land Survey

1 Corner 35 & 36; T.49 N., R.43 W.

, 19 <u>96</u> in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by William A. Burt on June 23, 1848. Original B.T.s ---Sugar 14" S.35 W. 14 links (9.24') --- Hemlock 16" N.35 E. 33 links Corner restored by Richard L. Drahn RLS 21564 on 12/7/80 by single proportionate methods. He set a 2" dia. iron pipe with a 3" stamped brass cap and the following new bearing objects: --- 5' (7") Yellow Birch N.60 E. (N.59 E.) 17.68' (17.63') --- 10" (12") White Ash S.31 W. (S.30 W.) 43.33' (43.32') --- 14" (15") Yellow Birch N.50 W. (N.51 W.) 30.25' (30.29") --- 7' Metal sign post S.56 E. (S.56 E.) 2.3' (2.2') ---

Corner recorded in Ontonagon County in Liber 1, Page 241 on 4/15/81.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Act 74 research form on file with Gogebic County records.

Recovered the monument as described and the bearing objects as noted in parentheses above.

No evidence of the original corner or bearing trees was found.

PEER GROUP, APPROVED COUNTY

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 67-08-96

New bearing tree referenced:

White Ash S.39 E. 11.52'

OF BICHIE RICHARD L DRAHN LAND SURVEYOR No. 21564

Lard P. Das

Date June 8, 1996