BURVEY REMONUMENTATION

APR 2 9 1996

COMMISSION

JUDITH D. ROEHM

12/28/95

Ontonason County 4/ 15 JEM LC

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

9.00 Fee: Page 1 of

For corners in

	Ontonagon (County)	-	Located In:	Corner Code :##
1.	Public Land Survey		τ <u>50N</u> R <u>39W</u>	E3
			T R	
			T R	<u></u>
			T R	
2.	Property Controlling	s	T R	
•	in Section	s	T R	<u> </u>
3.	Miscellaneous	s	T R	
	Property in Sec.	S	T R	


Register of Deeds Stamp & File Number

4. Lot No. ___ , Recorded Plat _

5. Private Claims

Lennis R. Destrampe in a field survey on October 5 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

Lynn 14 S25E 14 Y Birch 20 N40W 30 Corner shown on survey of section by Robert A. Mick, R.L.S. 16936, dated October 3, 1983, recorded in Survey Book 1, Page 68, Ontonagon County Register's Office. Corner recorded March 23, 1984, L.C.R.C. Liber 2, Page 150, by Robert A. Mick.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence found of original corner or accessories. Found a 2" capped pin as recorded, bearing trees gone due to clear cut logging, found stumps that fit bearing tree locations. Traversed perimeter of section, agreed within reason with Mick survey dimensions. Accepted corner as found. Research data on file with the county representative.

EER GROUP APPROVED



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Replaced ½" iron pin with a standard 2"x30" aluminum pipe monument with a 3½"

aluminum cap 0.5' above ground.

Cap stamped: COUNTY REMONUMENTATION

The following witnesses were established:

2" Sugar Maple 538° E 28.85' (Nail & tag "UPEA 18983") 8" Sugar Maple 557° W 46.24' (Nail & tag "UPEA 18983")

3" Ironwood S76°W 8.29' (Nail & tag "UPEA 18983")
4" Sugar Maple N28°W 65.11' (Nail & tag "UPEA 18983")
6' Steel Sign Post S49°W 0.61'

Surveyor's Michigan License No. .

T50N R39W

All bearing trees blazed and scribed NBT ned by Munis R. Westrampe

_ Date ______

PS 18983