

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>51</u> N. <u>37</u> E. R. <u>37</u> W.	<u>G9, H9</u>
2. PROPERTY CONTROLLING IN SECTION _____	T. _____ N. _____ E. S. _____ R. _____ W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ E. S. _____ R. _____ W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER _____

I, Keith L. Sackett, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on April 26, 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- Corner G9: Original corners and accessories not found. Found 2" iron pipe 4' high set by Copper Range.
- Corner H9: Original corner and accessories not found. Found 1 1/4" iron pipe set by Copper Range.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- Corner G9: Found 2" iron pipe 4' high set by Copper Range. Has been used as corner for many years.
- Corner H9: Found 1 1/4" iron pipe set by Copper Range. Has been used as corner for many years.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- Corner G9: 2" iron pipe 4' high witnessed by Regional Land Surveyor Billy D. Buckler 6/3/65.
 - 11" Maple N37°W (Mag.) 24.9' (S21, NBT)
 - 10" Sugar N30°E (Mag.) 19.2' (S22, NBT)
 - 7" Maple S25°E (Mag.) 23.2' (S28, NBT)
- Corner H9: 1 1/4" iron pipe x unknown length. Witnessed by Regional Land Surveyor Billy D. Buckler 6/3/65.
 - 10" Sugar S82°E (Mag.) 14.2' (1/4S, NBT)
 - 10" Sugar N20°W (Mag.) 48.0' (1/4S, NBT)


SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Keith L. Sackett DATE June 28, 1976
CHIEF OF SURVEY PARTY
MICHIGAN REGISTERED LAND SURVEYOR



SURVEYOR'S MICHIGAN REGISTRATION NO. 19006