## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T. 51N S., R. 37W E.	E13	
2. PROPERTY CONTROLL- 2	9 ,T. 51N N. 8., R. 37W E.	2	
	,TS., RE		
4. LOT NO, RE	CORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
I, Keith L. Sackett, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on			
Corner E13: Original monument and accessories not found. Found 1/2" I.D. iron pipe by unknown length located by Highway Department. Pipe is at old fence corner.			
Corner 2: Not set on original survey nor subsequently apparently.			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  Corner E13: Restored 5-22-79 at pipe. Fits good with other corners in area.  Corner 2: Established 5-25-79 midway and on line between corners.			
Corner E13: 1/2" 8" Su 7" Su	or corner and accessories establish  1.D. by unknown length i  1.gar S27°E 13.5 Ft.  1.gar S65°W 6.4 Ft.  1.gar N38°W 20.5 Ft.	ron pipe. S 2, NBT S 2, NBT	position of the corner:
<u>Corner 2</u> : Set 1-1, 5" Maple 5" Maple	/2" iron pipe.	/16 S, BT /16 S, BT	
SIGNED BY		DATE	•
SURVEYOR'S MICHIGAN R	EGISTRATION NO		(ØRAL)
FOR STATE AND UNITED STATES AGENCIES:			
SIGNED BY	CHIEF OF SUPPLY PARTY 1	DATE	The state of the s
APPROVED AND SIGNED BY CONTROL OF NATURAL REGISTERED LAND SURVEYOR  Keith L. Sackett  Michigan Dept. of Natural Resources  LAND SURVEY  NO.  19006			
SURVEYOR'S MICHIGAN REGISTRATION NO. 19006  FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION JAN 28, 1871 REVISED MAY 19, 1878			