LAND CORNER RECORDATION CERTIFICATE Unterseen County

Filing Requirement of Act 74, Mich. P.Aa1970 of 1 5/ 126 Ontonagon County Remonumentation Conterfee. Date 08/03/98 Time 09:21

> 2 3 4

10

11 12

For corners in

Ontonagon County	Located in:		Comer Code #	
1. Public Land Survey		T51N T T T	R37W R R R	I-12
Property Controlling in Section	S S	T	R R	
3. Miscellaneous Property in Sec	S	Ť	R	

RECOFCING FEE: 9, (111 .NK 1.1 1833 ROMONIS

Register of Deeds Stamp & File Number

Lot No.

, Recorded Plat

5. Private Claims

1, Joseph C. Domitrovich, in a field survey on July 3, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in fines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in

conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Law; established, re-established, monumented, recovered, found as expressed below:

A. Description of original monument and accessories and/or subsequent restoration:

(I-12) 1/4 Corner Common to Sections 34 & 35, T51N, R37W

1846 - Sylvester W. Higgins used 9" White Pine for corner post

I found no subsequent record.

9" White Pine N 70° W

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of the original corner or accessories. The area around the corner has been disturbed by North-South Van Damme Road. Van Damme Road runs generally North-South but does not follow the Section line and is not straight. I determined the Corner to be lost and re-established it by single proportionate measurement between Section Corners to the North and South.

Research on file with County Remonumentation Representative.

PEER GROUP APPROVAL CONSIL

JOSEPH

DOMITROVICH

LAND SURVEYOR ₩. **372**73

LANDES

poted.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 2 1/2" x 30" aluminum pipe with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; S.34, S.35; 1/4; T.51N, R.37W; 1998; P.S. 37273. The corner falls on Easterly edge of seasonal Van Damme Road.

Witnesses: 31.46 15" White Pine S 51° W 25.24 8" Balsam N 83° W SE Cor. Log Cabin N 29° W 94.10' **Power Pole** N 43° E 19.89 6.53 Steel Sign Post East N 01° 19' 17" W 2655.50 NW Cor. Section 35 SW Cor. Section 35 S 01° 19' 17" E 2655.50

(measured to corner of tin foundation)

NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object

GAC. Domit

7/22/98

Surveyor's Michigan License No. 37273