

✓  
MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 51N N.R. 41W


Ontonagon COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 8 - 9

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/16/65

WITNESSES TO CORNER..... 3" W. Spruce (1/8 NBT) N70°W 21.5'



6" W. Spruce " N76°E 14.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies in corner of spruce Plantation. Open Aspen to SW.

This corner replaced as set by unknown surveyor.

Found squared wood post in place.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 2/28/68  
REGISTERED LAND SURVEYOR