

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 51N N.R. 41W


Ontonagon COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 4-9

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 9/23/65

WITNESSES TO CORNER..... 9" Hard Maple (1/2 S NBT) N65°E 28.8'



CIRCLE CORNER REGISTERED

5" Hard Maple " N18°W 14.6'

5" Y. Birch " S85°W 7.1'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two Section Corners.

Found no evidence of original corner.

Corner lies 50' North of road shoulder.

SURVEYOR'S SEAL

Billy D. Buckler

SIGNED Billy D. Buckler DATE 2/28/68
REGISTERED LAND SURVEYOR