## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION



## LAND CORNER RECORD

T. 52 N.R. 37W

Ontonagon County

DESCRIPTION OF CORNER Section Corner co mon to Secs. 1 23-24-25-26

CORNER MONUMENT 1½" Iron Pipe

DATE MONUMENT PLACED AND WITHESSED 5/14/64

WITHESSES TO CORNER..... 7" Mard Maple (S24 NBT) N E Lits.

7" Mard Maple (S23 NBT) N W Lits.

AND

## DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was re-witnessed as set by unknown Surveyor. Found old blaz es to East, West and North. Distance East to an Original 1/4 Corner is 35.30 chains. Record indicates 40.02 chains.

SHRYEYOR'S SEAL

CIRCLE CORNER REGISTERED

Billy D. Buckler

BY D. RHOWELLE BATE 8

TORED \_\_\_\_\_

DATE 8/5/1964