## SUHVEY & REMONUMENTATION

APR 2 6 1996

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Requi	rement of Act 74	I, Mich. P.A. 1970	. Ella	
ONTONAGON	Located In:	Corner Code	e <i>=t</i> .#		
Public Land Survey	39 T 52 R 💯 T 52 NR 38 V T R	M-2 A-2		Hecorded October 19 rg of at 2:13 o'check M. Liber 3 page 212 Register at Decels	7.4 Ey
in Section S _ 3. Miscellaneous S _	T R T R T R			ster of Deeds Stamp & File Number	
4. Lot No, Record					
5. Private Claims				A B C D E F G H I J K	+
1/4 Corner Section	n 1 & 6, T52N	R38W &R39W		3	-
Earl W. Applekamp	field survey on Sep	tember 15,	. 19 94	5	-12 <u>-</u>
do hereby certify that under requirement lines 1 and 2 above were in contacurrent manual of survey instructions. Management or by a decree of a Court above were in conformance with the recourt of Law; established, re-estate expressed below:	rmance with regulations at of the United States Depa of Law and/or that the cornutes of the Michigan Board blished, monumented, re-	nd rules therefore as diment of the Interior er points mentioned i of Land Surveyors or monumented, recov	s required in the , Bureau of Land in lines 3, 4 and 5 by a Decree of a vered, found as	6	
NOTE: Not more than 4 corners on this certificate.	, all in the same town a	nd range, may be		11	-36-
A. Description of original monun	nent and accessories an	d/or subsequent r		13	
Alder Post			r	ONTONAGON COUNT	' <b>W</b>
Fir Sugar		16 Links 16 Links	(10.56') (10.56')	PEER APPROVED	Ţ
			,	Lack W Appleka Ontonayon Co. Let	a.
B. Description of corner evidence	e found and/or method	applied in restorin	g or reestablishing c	10-12-4	,
The corner was the NE and SE in agreement s	s set by single corners of the with the call is set at the pos:	e proportio e Section. to the Fire	nate measure The corner steel River.	ment between position is	
Research on f Representativ	ile with Count e	y Remonumer	itation	EARL W. A APPLEKAMP PROFESSIONAL SURVEYOR NO. 17610	
C. Description of monument for o	corner and accessories		petuate localing the p	position of the spring.	
a 3 1/4" cap, 6, T52N, R38W,	position I se stamped to rea R39W, 1994, I used to tie the	ad: County P.S. 17610.	Remonumentat The follow	ion 1/4 s- 1,	
Hard Maple Hard Maple		27.88! 8.80'	Soft Maple Steel Sign	N08°E 9.11' Post East 1.40'	
Signed by Lack W	appleka	up	Date Oc	tober 07, 1994	·
Surveyor's Michigan License No	X7610	;	FORM APPROVED	BY MICHIDAN STATE BOARD OF LAND SURVEYORS, JAH. 28 Revisco may 14 Reviseo Jan	1975