## SUHVEY & REMONUMENTATION -

APR 2 9 1996

JUDITH D. ROEHM Ontonagon County 10/19/95

13:41

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Feet 3/ 334 JEN Fage

For corners in	Finng Require	ement of Act 74, which. P.A. 19	770
Ontonagon (County)	Located In:	Corner Code #	
1. Public Land Survey	T 52N R 39W T R R T R	D-9	
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Section</li> </ol>	S T R S T R S T R		Register of Deeds Stamp & File Number
5. Private Claims			A B C D E F G H J K L !
do hereby certify that under re in lines 1 and 2 above were in manual of survey instruction Management or by a decree of 5 above were in conformance	equirements of P.A. 74, Michigan P./ conformance with regulations and r ns of the United States Departm of a Court of Law and/or that the co e with the rules of the Michigan Bo	A. of 1970, the corner points mentioned ules therefore as required in the current nent of the Interior, Bureau of Landorner points mentioned in lines 3, 4 and pard of Professional Surveyors or by a ted, re-monumented, recovered, found	8 19 -20 -21 -22 -23 -24 - 9 10 30 - 29 -28 -27 -26 -25
on this certificate.	orners, all in the same town and	• • •	12 31 32 33 34 35 36
1/4 Corner, Sections 20 a		navor subsequent restoration.	

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found no evidence of original corner. Found a bent rerod 3" below paved surface of Paul Bunyan Ave. The rerod falls on centerline and on the extension of a fallen fenceline to north. Corner also falls within 0.2' of a perfect split of the distance between section corners.

Accepted corner position and replaced with a county monument.

1845 - William A. Burt set 1/4 section post

6" Fir

18" Sugar

N 860 E

N 370 W

(Research on file with County Remonumentation Representative.)

C.	Description	of monument fo	r corner and	accessories	established	l to perpetua	ate locating the	position of	of the corner:
Corr	ner is a 5/8"	rerod with a 3"	diameter st	amped alum	inum cap a	and falls on	centerline of F	Paul Buny	an Ave.

Witnesses:

Power Pole 12" Ash

N 400 E S 35° E

45.15

29 links

34 links

4" Ash

S 210 W

46.50'

25.02'

Reference Monument (Aluminum pipe with stamped Aluminum cap) Sign Post

North

25.84

PEER GROUP APPROVED

COUNTY

NOTE: Bearings are magnetic. Distances are to nail in side of witness objects unless noted.

Surveyor's Michigan License No.

REVISED MAY 14, 1975 REVISED JAN., 1983

JOSEPH