SUHVEY & REMONUMENTATION

JUDITH D. ROEHH Untenagon County 03.19796

47 134 JEM LC

DEC 1 6 1996

ANTON IN STATE OF A PROPERTY AND A MARKET AND ASSESSED.

LAND CORNER RECORDATION CERTIFICATE

Feet		in l	II
Page	1		1

GOMMI For corners in	SSION Filing Rec	quirement of Act 74, Mich. P	'.A. 1970
Ontonagon (County)	Located In:	Corner Code #	1
Public Land Survey	T <u>52N</u> R40 T R T R T R	•	
Property Controlling in Section Miscellaneous	S T R S T R S T R		
Property in Section	S T R		Register of Deeds Stamp & File Number
I. Joseph C. Domitrovich do hereby certify that under rein lines 1 and 2 above were in manual of survey instructio Management or by a decree 5 above were in conformance Decree of a Court of Law; es as expressed below: NOTE: Not more than 4 con this certificate.	, in a field survey on	June 20 , 19	2 6 5 4 3 - 2 10 11 12 12 13 14 13 14 15 14 15 14 15 14 15 14 15 14 15 14 15 14 15 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15
A. Description of origina	al monument and accessorie	es and/or subsequent restoratio	yn:

(L-11) 1/4 Corner common to Sections 25 & 36, T52N, R40W

1845 - William A. Burt set post of Tamarack

4" Ѕргисе N 400 W 4" Tamarack

S 850 E

47 links 67 links

1923 - E.J. Donnelly C.E. re-established this corner by single proportionate measurement and set a 3" iron pipe. He used this corner in two plats dated the same year. He indicated corner worked well with old fence intersection.

1991 - Brian Taavola P.S. 21583 found a 3/4" drillrod in a 9" concrete monument in a swamp as per old Highway plans, and recorded it in Liber 3 page 150 of corner records.

1991 - U.S. Army Corps of Engineers found and used the recorded corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found no remains of original corner or accessories. Found the 3/4" drillrod and witnesses as recorded by Taavola. Drillrod falls 2635.21; east of Section corner to west. (Donnelly measured 2635.38' in 1923).

I accepted the drillrod as the 1/4 corner. It falls in a narrow swampy area. I left the drillrod in place and established two reference monuments, one on the north and one on the south side of the swamp.

Research on file with County Remonumentation Representative.

PEER GROUP

07-08-96 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 3/4" drillrod in concrete. Established two reference monuments (R.M.) each a 2" x 30" aluminum pipe with a 3" diameter aluminum cap stamped to indicate bearing and distance to corner. *Note - Corner does not fall on straight line between reference monuments. OF MIEN

Witnesses:

Lightning rod atop wide smokestack at paper mill bears N 130 20' 10" 1515' +/-

N 01^o 37' 08" W S 03^o 22' 43" E. R.M. #1 50.85 R.M. #2 25,941 S 89° E 6" Poplar 85,70 (Existing) N 770 E Power Pole 75.47' (Existing) N 850 W Power Pole 201.94

Steel Sign Post West 0.71 NOTE: Bearings are magnetic. Distances are to nail in side of witness objects unless noted.

Somith _ Date <u>7/3/96</u>

37273 Surveyor's Michigan License No.__

FORM APPHOVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

JOSEPH

DOMITROVICE

ана 3.