

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 53 N.R. 37 W


Ontonagon COUNTY

DESCRIPTION OF CORNER Section Corner common to Secs. * 17-18-19-20

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 1/27/1965

WITNESSES TO CORNER..... 12" Hemlock (S17 NBT), N 50° E, 53 1/2 Links



10" Cedar (S18 NBT), N 50° W, 81 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced at old Cedar Post with remains of one Y. Birch B.T., bearing N 42° E, 30 Links. Stub remains with part of both faces in evidence. Corner in cutting edge to East and West.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE April 17, 1965
REGISTERED LAND SURVEYOR