

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



# LAND CORNER RECORD

T. 53 N.R. 38 W


Ontonagon COUNTY

DESCRIPTION OF CORNER Section Corner common to Secs. 13-14-23-24

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 3/25/65

WITNESSES TO CORNER..... 10" Soft Maple (S14 NBT), N 02° E, 49 Links



13" Soft Maple (S23 NBT), S 80° W, 18 1/2 Links

9" Soft Maple (S24 NBT), S 46° E, 23 Links

AND

CIRCLE CORNER REGISTERED

## DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced at location of two old Wood Posts; Several blazed trees with old signatures and at intersection of blazed lines from East, South, North Position checks with distance to river, West and South.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE April 7, 1965  
REGISTERED LAND SURVEYOR