MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 53 N.R. 38 W

	Ontonagon	COUNTY
DESCRIPTION OF CORNER North 1/16 Corner Section	22	
CORNER MONUMENT 1" Pipe with 4" Aluminum Cap		
DATE MONUMENT PLACED AND WITNESSED3/24/65		
WITHESSES TO CORNER 10" Cedar (N 1/16 BT), S	26° B. 16 Links	
10" Cedar (N 1/16 S22 BT)	, S 66° W, 24 Links	
CIRCLE CORNER REGISTERED		· · · · · · · · · · · · · · · · · · ·

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was established midway between 1/4 Corner to North and Center of Section to South.

SURVEYOR'S SEAL

Silly D. Suchler.

SIGNED Billy D. Buckler DATE April 7, 1965