

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 53 N.R. 38 W


Ontonagon COUNTY

DESCRIPTION OF CORNER East 1/16 Corner between Secs. 14 and 23

CORNER MONUMENT 1" Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 3/25/65

WITNESSES TO CORNER..... 13" Cedar (1/16 Corner BT), S 11° W, 32 Links



10" Cedar (1/16 14/23 BT), S 79° W, 53 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was established midway and on line between Section Corner to East and 1/4 Corner to West.

Corner lies in Swamp, 50 Links North of ridge.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler DATE April 7, 1965
REGISTERED LAND SURVEYOR