## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 53 N.R. 38 W

	Ontonagon	COUNTY
DESCRIPTION OF CORNER 1/4 Corner between Secs.	22-27	
CORNER MONUMENT 1" Pipe with 4" Aluminum Cap	· · · · · · · · · · · · · · · · · · ·	
DATE MONUMENT PLACED AND WITHESSED 3/25/65		
WITHESSES TO CORNER 11" Hemlock, (1/45 NBT).	N60° E, 612 Links	
12" Soft Maple (1/4S NBT	), S 19° E, 72 Links	
CIRCLE CORNER REGISTERED		

## DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from one original Hemlock bearing tree, S 40° E, 07 Links. Chopped out overgrowth about 5° deep to Original face and scribe marks. Tree is still green.

SURVEYOR'S SEAL

Signed Billy D. Buckler DATE April 7. 1965

REGISTERED LAND SURVEYOR