## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. \_\_\_\_53 \_\_\_ N.R. \_\_\_38 W

		Ontonagon	COUNTY
DESCRIPTION OF CORNER _	Center of Section 2	22	
CORNER MONUMENT	1" Pipe with 4" Aluminum	1 Cap	
DATE MONUMENT PLACED AN	ID WITHESSED3/26/65		
WITHESSES TO CORNER	8 Cedar (S 22 BT), S	30 W. 23 Links	
N	8 Cedar (S 22 BT), S	3 21° E. 35 Links	
22			<del></del>
CIRCLE CORNER REGISTERS	AND		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was established at Inter-section of lines connecting the opposite 1/4 Corners of Section 22.

SURVEYOR'S SEAL

DATE \_April 7 1965