

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 53 N.R. 38 W


Ontonagon COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 21-22

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 6/4/65 Distances in Feet

WITNESSES TO CORNER..... 13" Cedar (1/4S NBT), S 84° E, 28.0'



11" Y. Birch (1/4S NBT), S 24° W, 22.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner replaced from one Soft Maple B.T., bearing S W, lks. Tree green with face rotted.

Corner lies in old N-S road.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 4/29/1966
REGISTERED LAND SURVEYOR