

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 53 N.R. 38 W


Ontonagon COUNTY

DESCRIPTION OF CORNER 1/4 Corner between 26-27

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 5/25/65

WITNESSES TO CORNER..... 15" Hemlock (1/4S NBT), N 07° E, 40 Iks.



6" Cedar (1/4S NBT), S 70° W, 29 Iks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from two Hemlock stumps bearing N 45° W, 24 Iks.,  
and S 35° E, 21 Iks.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler  
Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE 4/29/1966