CONS. 4047 4/86

MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 33 NR 4 E

		Presque	1816	COUNTY
DESCRIPTION OF CORNER	Section corne	er common t	o Section	ns 10-11-14-15
DESCRIPTION OF CORNER	MONUMENT	pipe_with_4	"_brase_	cap
WITNESSES TO CORNER				
	6" Cedar	- N49W	_	33½ Links
	6" Spruce	- s40E	_	8½ links
	6" W. Pine	- s 35 w	-	46½ links
				- -

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a survey of Section 15. Restored corner from NE government BT-- a 10" Cedar longbutt showing marks. Could not find post in roots of other small Cedars. Checks with good 1/4 corner south.

Conner was placed and witnessed May 4, 1960.

SURVEYORS SEAL

SIGNED LEMEL & Velling DATE 5/6/60
REGISTERED LAND SURVEYOR