LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

_		* _
FOR	COLUMN	תו


Presque Isle	Located In:	Corner Code ##
Public Land Survey	T R T R T R T R	
Property Controlling in Section	S 27 T 33N R 4E S 27 T 33N R 4E	15 16
Miscellaneous Property in Sec.	S T R S T R	<u> </u>


Register of Deeds Stamp & File Number

_ , Recorded Plat . 4 Lot No. Private Claims

I, Carl R. Johnson , in a field survey on March 17 & May 23, , 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.





- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 15 Set midway and on line between section corner and 1/4 corner.
 - 16 Set midway and on line between section corner and \(\frac{1}{4} \) corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

15 - W 1/8 Corner on S. Side

16 - E 1/8 Corner South Side of Sec. 27

15 - W 1/8 Corner on S. Side Set 5/8" bar & sq. Cedar Post 6" Cedar N57 E 7.2' 6" Cedar S40 W 8.5'

5/8" bar w/cap, Cedar Post Cedar 6" N 9 E 10.9' Cedar 6" 10.9 N79°W Cedar 10" 5.3' S 8°E Cedar 8" 14.3'

JOHNSON JRVEYOR N٥. 30083

Surveyor's Michigan License No. 30083

6" Cedar