

8620

1999 PRESQUE ISLE COUNTY, STATE OF MICHIGAN REMONUMENTATION

DEC 29 1999

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Presque Isle
(County)

Located In:

Corner Code #

1. Public Land Survey

T 34 R 4E

B-5

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

PRESQUE ISLE COUNTY
RECORDED
1999 DEC -2 PM 2:13
Janet M. Lamb
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Delmer E. Porter in a field survey on Nov. 12, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													


A. Description of original monument and accessories and/or subsequent restoration:

B-5 GLO Notes - 1856
Set Quarter Section Post
6" S Pine N46°E 14 Lks
5" S Pine S28°W 6 Lks

C Kiiskila #33981
Liber 322, Pg 429 & L 1, Pg 1014
Set DNR Mon and Set Carsonite
Post 11' South
Chiseled X in Stone N74°E 11.21'
Chiseled X in Stone N04°E 19.79'
Chiseled X in Stone N64°W 18.21'
Fd 1/2" Rerod South 4.18'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

B-5 Fd DNR Mon & Carsonite Post
Chiseled X in stone N74°E 11.21'
Chiseled X in stone N04°E 19.79'
Chiseled X in stone N64°W 18.21'
Fd 1/2" Rerod South 4.18'



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-5 1/2" Rod
S07°W 4.20'
N65°W 18.21' X Chiseled in Stone
N04°E 19.83' X Chiseled in Stone
N45°E 21.20' S Edge of N. Quarry Pond
N74°E 11.23' X Chiseled in Stone

Ratified by Peer Group
in accordance with P.A. 345

Chairman *Norman J. Omsini*
Date 11/30/99

*Witness tags & nails used.

Signed by *Delmer E. Porter*
Surveyor's Michigan License No. #15410

Date 11-15-99