

1998 PRESQUE ISLE COUNTY, STATE OF MICHIGAN REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

or corners in

Presque Isle (County)	Located In:	Corner Code #
Public Land Survey	T34NR 4E	H-11
	T R	
	T R	
	T R	
Property Controlling in Section	S T R	
	S T R	
Miscellaneous	S T R	
Property in Sec.	S T R	

PRESQUE ISLE COUNTY  
RECORDED

98 DEC 17 PM 4: 27

*Jane M. Lamb*  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Delmer E. Porter a field survey on Jan. 9, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, discovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

H-11 GLO Notes	N40°W 57.35' P. Pole
June 27, 1856	South 33.23' Cor Fence Post
Set Quarter Section Post	N15°E 60.28' 10" Elm
Y. Birch 8 N10W 36 Links	
B Ash 8 S10E 42 Links	

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-11 1/2" Rod & Cap in Mon Box  
S08°E 47.30' 6" Cedar

SURVEY &  
REMONUMENTATION

JAN 14 1999

SECTION

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-11 1/2" Rod & Cap #15410 in Mon Box  
S59°E 48.25' 19" Aspen  
S01°W 47.35' 10.5" Cedar  
S67°W 62.66' 6"X6" FE Post/RR Tie  
N42°W 48.41' #HK4 Telephone Pole



Ratified by Peer Group  
in accordance with P.A. 345,  
Chairman *Norman J. Quenneville*  
Date 12/17/98

by *Delmer E. Porter*  
Surveyor's Michigan License No. #15410

Date Dec 9, 1998