LAND CORNER RECORDATION CERTIFICATE

F	Filing	Requirement of A	ct 74, Mich.	P.A. 1970)		
For corners in				1			
PRESQUE ISLE	Located In:	Corner Code #					
(County)							
Public Land Survey	T_34NR_ TR_ TR_	4E C-4					
Property Controlling in Section Miscellaneous	TR_ S TR_ S TR_ S TR_	14					
Property in Sec.	S IR_				Register of	Deeds Stam	p & File Number
4. Lot No, Reco 5. Private Claims	rded Plat				ABCD	E F G I	I J K L
			· · · · · · · · · · · · · · · · · · ·		2 6 5	4	32-1-
					3		- - - -
requirements of P.A. 74, Michiga	, in a field survey on <u>fial</u> an P.A. of 1970, the corner	points mentioned in lines	1 and 2 shows	were in	4 - 7 - 8	b	01112
conformance with regulations and United States Department of the	d rules therefore as required	in the current manual of s	unaw inetruction	e of the	5		
that the corner points mentioned Board of Land Surveyors or by	d in lines 3, 4 and 5 above w	ere in conformance with ti	he rules of the M	lichigan	6 -18 -17	161	51413
recovered, found as expressed be	elow:	Law, established, re-est	aciisnea, monur	nentea,	8 —19——20	212	2 23 24
NOTE: Not more than 2 con	ners, all in the same town	and range, may be reco	orded		9		
on this certificate.				:	.0-30-29	282	72625
				:	1		
					2 31 32	33-1-3	4 35 36
A. Description of original mo C-4 (NO EVIDENCE OF 6.L.O. COP AS CALLED DUT IN THE 6.L.O BELOW.)	RNER, B.T'S, LINE TREES	& TOPOGRAPHY,	estoration; 14				
B. Description of corner evid	dence found and/or meth	nod applied in restoring	or reestablish	nina corner			
C-4 Reestablished the E1/4 Cor						of the CE 1	/A of Cor
found NE and SE corners of	Sec. 7.		per standard			or the sc 1.	/4 OT SEC.
C. Description of monument	for corner and accessori	es established to perp	etuate locating	the position	n of the corne	r:	j
C-4 Set D.N.R. Mon.		Sat	14 : 5/8"x 34" re	200 H/PG	an and careon	ita anet 🗻	LEELL.
24" R.Pine S34°E	62.30'	8*	R.Pine	528°W	64.68'	و عالمهمو	F MICHIGA
12" Cak N63°W 20" Cak N20°W	91.22′ 106.04′		•	563°W 582°W	12.16' 37.89'	7 ~	CARL
N-S trail road 300'+/- Eas			uahta	202 W	37.07	7 . •	IISKILA LAND ★
						7 7 -	RVEYOR
						15.	No. 33981
						NENSED	LAND SURVEY
Signed by Can	& T. Kisk	L.	5 /	5- Z	9-02	. John	CHIAN
Surveyor's Michigan License I		33981	Date		/ //		