

96 JUN -4 AM 11:23

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Presque Isle (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>34</u> N R <u>5</u> E	A-1
	T ___ R ___	___
	T ___ R ___	___
	T ___ R ___	___
2. Property Controlling in Section	S ___ T ___ R ___	___
	S ___ T ___ R ___	___
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	___
	S ___ T ___ R ___	___

Janet M. Lamb
REGISTER OF DEEDS

RECORDATION

JAN 22 2001

SECTION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Norman J. Quaine in a field survey on Dec. 12 19 95 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

A-1	1840	1856	Feb. 24, 1942	May 5, 1948
Township lines by	John Hodgson	Re-examined by	G.A. Delamater	Survey by Donald A. Marlatt-R.S. Scotts & Ass
Deputy Surveyor	Set Post	Alfred Millerd	Reg. Surveyor	Alpena, (Not recorded)
Beech 8 S70W 10	Do 8 N83E 17	No witness given	Called for	Survey shows section
		Assumed to be	(1/2"X48" Bar)	breakdown w/no reference
		same as Hodgson	Fd. pipe in cor.	to physical corners

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-1	December 12, 1995	Fd. R.R. Spike	Feb. 16, 1976
Norman J. Quaine	PS#33984, Porter's Survey P.C.	N62°W 97.72' 7" Cedar	LCRC, Delmer E. Porter
1996 P.I. Co. State Remonumentation		S47°W 52.18' FE Cor.	LS#15410
			1 1/2" Pipe by Loud
			N48°E 56.0' 4" Cherry
			S52°W 163.0' 24" Beech
			Old 1/2" Rod
			N62°W 98.31' 5" Cedar
			N67°E 132.95' Utility po.
			S33°W 57.71' FE Cor

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-1	Left R.R. Spike	Ratified by Peer Group	Sept. 29, 1978
N62°W 97.72' 7" Cedar	S47°W 52.18' FE Cor	in accordance with P.A. 345	LCRC, Delmer E. Porter
S52°E 70.76' P. Pole	N09°E 59.83' 7" Scotch Pine	Chairman <i>Delmer E. Porter</i>	LS#15410
		Date <u>5/22/96</u>	Fd 1/2" Rod 1.5' deep
			Raised with 1/2" Rod
			N62°W 98.07' 4" Cedar
			S47°W 51.80' FE Post
			S56°E 63.83' P. Pole

*Witness tags & mails.

Porter's Survey P.C.

Signed by Norman J. Quaine
Surveyor's Michigan License No. 33984

Date MAY 29, 1996