1996 PRESQUE ISLE COUNTY, STATE OF MICHIGAN REMONUMER RECORDED

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

96 JUN -4 AM 11: 23

For corners in			
D			(humanana)
Presque Isle Locat	ed In: Corner Code #	;	REGISTER OF DEEDS
(County)			REGISTER OF DEEDS
1. Public Land Survey	184N R 5E A-2		
•	TR	<u></u>	-
	TR		
	<u>TR</u>		
2. Property Controlling S	. <u>T R </u>		•
in Section S	<u> </u>		
3. Miscellaneous S Property in Sec. S	· · · · · · · · · · · · · · · · · · ·		
riopeity in Sec.	. ''	·	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	·		
4. Lot No, Recorded Plat 5. Private Claims			A B C D E F G H I J K L N
·			2 - 6 - 5 - 4 - 3 - 2 - 1 -
			3
Norman J. Quaine in a field survey on Dec. 8, 19 95do hereby state that under			4 7 8 9 10 11 12
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in			5
conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or			
that the corner points mentioned in lines 3,	reau of Land Management of by a decr 4 and 5 above were in conformance w	ree of a Court of Law and /or ith the rules of the Michigan	6 18 17 16 15 14 13
Board of Land Surveyors or by a Decree	of a Court of Law; established, re	established, monumented,	7
recovered, found as expressed below:			8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in	the same fown and range, may be a	recorded	9
on this certificate.		10 30 29 28 27 26 25	
			11
			12 31 32 33 34 35 36
A. Description of original monument a	and acceptation and/or subseque	nt restoration:	1.5 market and the second and the se
A. Description of original monument a A-2	ild accessories aridior subsequer	it restoration,	
1840	1856	LCRC	
Twp. lines run	Re-established	Sept. 28, 197	78
by John Hodgson	W. Township line	Delmer E Por	
Deputy Surveyor	Reset all corners	#LS #15410	
Cedar 10 S39E 11	Set 1/2 Sec. Post	Fd 1/2" Rod	
B. Ash 11 S85°W 5	Beech 15 N68W 12	N46°E 69.58'	
	Sugar 10 S48E 2	Due E 53.23'	
		S45°E 58.80'	
B. Description of corner evidence fou	nd and/or method applied in resto	oring or reestablishing corn	er: LCRC
A-2	_		Nov. 9, 1979
Dec. 8, 1995	Fd. Conc. Mon/Bra	Delmer E. Porter	
Norman J. Quaine	N46°E 69.61' 14"		LS#15410
P.S.#33984, Porter's Survey P.C.	S87°E 53.46' 28"		Fd 1/2" Rod & Set Conc
1996 P.I. Co. State	S45°E 58.93' 7" I	HemTOCK	Mon with brass cap
Remonumentation			N46° E 69.58' 12" Maple
icinomandioa o 1 o ii			Due E 53.23' 22" Hem. S45° E 58.80' 5" Hem.
			545 E 56.00 5 Hem.
			447 4.43
C. Description of monument for corne	r and accessories established to p	perpetuate locating the pos	ition of the corner:
A-2			<u>~</u>
Left Conc Mon/Brass Ca	g		
N84°W 33.36' P. Pole	-		d by Peer Group
N46° E 69.61' 14" Maple		in acco	ordance with P.A. 345
S87° E 53.46' 28" Hemlo	cok	ੌ Chairr	nan Delmer Etra
S45° E 58.93' 7" Hemloo	!k		
		Date _	5/22/96
*Witness ta	igs & nails.	Chaim Date _	
Porter's Survey P.C.		F.	ور
al source 1		. 1.	20 1901
Signed by Norman July	ame.	Date <u> </u>	1 29,1996.
Surveyor's Michigan License No. 3	3984		