## 1996 PRESQUE ISLE COUNTY, STATE OF MICHIGAN REMONUMENTATION

LIBER 318 PAGE 626

## LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Require	ement of Act 74, Mich. P.A	. 1970
Presque Isle	Located In:	Corner Code ##	PRESQUE ISLE COUNTY RECORDED
Public Land Survey	T_34NR_5E	В-3	**************************************
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	T R		96 JUN -4 AM 11: 25
	T R		
O Premarks Controlling C	T R T R		lang more
	T R		REGISTER OF DEEDS
	T R		Register of Deeds Stamp & File Number
Property in Sec. S	T R		
	. J. Di 4	•	
4. Lot No, Recorde 5. Private Claims			A B C D E F G H I J K L
J. Thrace Oralins			2 - 6 - 5 - 1 - 3 2 1 -
,		,	3 + + + + + + + + + + + + + + + + + + +
Norman I Ovaina	Dogo	mbor 0 m 05	4 - 7 - 4 - 8 - 4 - 9 - 4 - 10 - 4 - 11 - 12 -
(, Norman J. Quaine in a tid do hereby certify that under requirement	ield survey on <u>Decel</u> nts of P.A. 74.Michigan P.A.	of 1970, the corner points mention	ned 5
in lines 1 and 2 above were in conform	mance with regulations an	d rules therefore as required in	the 18 1/ 10 13 14 13
current manual of survey instructions of Management or by a decree of a Court of	of the United States Depart of Law and/or that the corne	tment of the Interior, Bureau of La er points mentioned in lines 3, 4 an	
above were in conformance with the ru	iles of the Michigan Board o	of Land Surveyors or by a Decree :	ofa oli i i i i i i i i i i i i i i i i i i
Court of Law; established, re-estable expressed below:	lished, monumented, re-r	nonumented, recovered, found	as 10 30 29 28 27 26 25
NOTE: Not more than 4 corners,	all in the same town ar	nd range, may be recorded	11
on this certificate.			12 31 32 33 34 35 36
A. Description of original monume	ent and accessories and	d/or subsequent restoration:	13
B-3		N#0 0	1070
July 19 +/-, 1856 Sec. Subdivision by	Sept. 29, 19	9/8 NOV. 9 LCRC	, 1979
Alfred Millerd	Delmer E. Po	<del></del>	E. Porter LS#15410
Deputy Surveyor	LS #15410	Fd 1/2	" Rod/replaced with conc.
Set Quarter Sec. Post			th brass cap
Hemlock 12 N60W 28 Beech 11 S52E 22	1/2" Rod in Due N 32.40	•	32.40' FE Cor 35.57' 3" Cedar
Beech 11 3326 22		' 3" Cedar Due S.	
	Dua S 30 42	FE Cor	
B. Description of corner evidence	e found and/or method	applied in restoring or reestat	ousning comer:
B-3			
December 8, 1995	Fd. Conc Mon.		
Norman J. Quaine	Put cap #3398		
PS#33984, Porter's Survey P.C.	203 M 32 02	P. Pole (Beck's)	
1996 P.I. Co. State			
Remonumentation			
		tablished to perpetuate les	nting the position of the corner.
C. Description of monument for c	corner and accessories	established to perpetuate too	ating the position of the comer.
B-3 Left Conc Mon & Cap 4	#33984 in C/L ]	Rđ.	
S03°W 32.62' P. Pole	., -		salfied by Door Croup
			latified by Peer Group
N20° W 84.43' SE cor House in accordance with P.A. 345			
N14°W 106.94' NE Cor House			chairman
*Witness	tags & nails.	C	ate 5/22/96
Porter's Survey Pi	C. March Tall		
Signed by Asman Like	ami	Date^	PAY 29, 1996
Surveyor's Michigan License No.	33984		FROM ADDDONER OF MINUSAN STATE BOARS OF LAND SUBVEYORS IN THE T
Surveyor S who higan License No			FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 11 REVISED MAY 14, 11

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983