## LAND CORNER RECORDATION CERTIFICATE LIBER 318 PAGE 727

Filing Requirement of Act 74, Mich. P.A. 1970						
For corners in	Te16	Located in:	•	Corner Cod	le #	
Presque	unty)		•			PRESQUE ISLE COUNTY RECORDED
1. Public Land	Survey	τ	N R <u>5E</u> _ R	D-9		96 JUN 13 PM 12: 24
			_ R _ R			
2. Property Cor	ntrollina	s	'' R		, i	Line M. Samb REGISTER OF DEEDS
in Section		ST	_ R			REGISTER OF DEEDS
3. Miscellaneou	IS	s T				•
Property in S	Section	s T	_ R	<del></del>	['	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat A B C D E F G H t J K						
5. Private Claims						
			,			2 - 5 - 1 - 5 - 1 - 3 - 1 - 2 - 1 - 1
•					`	3 1 1 1 1 1 1 1 1
L Bonnal d. Districtions in a field survey on 2 27 40 06						, [ ]   1   1   1
l, Ronald Bischer, in a field survey on 3-27, 19 96 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned						
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current						
manual of survey instructions of the United States Department of the Interior, Bureau of Land						
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a						
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found						
as expressed below: 10 30 29 28 27 26 2						
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.						11 32 33 34 35 35
13 1 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3						
A. Description	•	nument and ac	cessories and/or	subsequent	restoration:	
	D-9					
	1856 A1:		end Set W		t	
			8" Beech 8" Beec			
	570 E	30 TINKS	о веес	11		
4-4-78 Delmar Porter found 1" Rod (Scott 1955), set $1/2$ " rod in						
Mon. box. left 3 witnesses						
3-25-94 James Beck found $1/2$ " Rod & Cap $#15410$ in Mon Box						
left 5 witnesses						
B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:						
•	D-9		• •			-
		Ronald B	ischer Fo	und 1/2	" Rod & Ca	p #15410 in Mon. box
	S66°E	86.54'	18" Maple	stump		The state of the s
	N70°E	42.80	Urd cable	marker	post	COUNTE OF MICHIES
	S50°W	50.25	Stop sign	post		RONALD
	\$70°W		4" Apple			BISCHER :
	N46 <sup>8</sup> W	40.30'	P.pole			LAND
						SURVEYOR
						NO. 22428
						A. C.
						THE DEAND SUMMED TO
C. Description	of monument	for comer and a	accessories estal	blished to pe	rpetuate locating	g the position of the comer:
	D-9					
	3-27-96	Ronald B				
	1/2" Ro	d & Cap #	15410 in M	on. Box	1	Ratified by Peer Group
	S66 E	86.54	18" Maple	stump	(deg	in accordance with P.A. 345
	N63 E	42.80	Cable pos	τ	'je'	Chairman Delmu Anla
	555 o W	47.02' 80 KOI	Stop sign 4" Apple		; .	* . \
	N420 M	40.30°	Power pol	e		Date
	14 15 11	10.00	TOUCT POT	~		-
					·-	
Signed by R	nall	P. Bi	elu-		Date <i></i>	-6-96
Surveyor's Michigan License No. 22428 FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 29,						