

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

DEC 22 AM 9:56

For corners in

<u>Presque Isle</u> (County)	Located in:	Corner Code #
1. Public Land Survey	T <u>34</u> N <u>R</u> <u>5E</u>	<u>J-11</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

Janet M. Lamb
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Ronald Bischer, in a field survey on Oct 1, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

J-11
GLO Notes
Alfred Millerd
1856 Resurvey
Set post
Tamarack 10" N45° E 16 lks
Tamarack 8" S10° W 20 lks

1989 Norman Quaine #33984
Found 1/2" Rod and Cap #15410
Set three witnesses


B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J-11 Found 1/2" Rod and Cap #15410
and Two Quaine witnesses

SURVEY &
REMONUMENTATION

JAN 14 1998

SECTION



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-11
1/2" Rod and Cap #15410
N42° E 14.69' 6" Cedar Quaine Witnesses
S27° E 7.36' 12" BALSAM Quaine Witnesses
N61° W 9.60' 4" Cedar
S64° W 27.45' 4" Cedar

Ratified by Peer Group
in accordance with P.A. 345
Chairman *Norman Quaine*
Date 10/30/97

Signed by Ronald R. Bischer
Surveyor's Michigan License No. 22428

Date 10-8-97