

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T 35 NR 4 E  
T 36 NR 4 E

Presque Isle COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 3-4-33-34

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

10" Hemlock	-	N78E	-	39 links
8" Hemlock	-	N65W	-	20½ links
5" Cedar	-	S55W	-	33 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a survey in this area. Found an old scribed post at corner with another stake point below. The SE government longbutt Hemlock in place with very good upper face and marks. The SW gov't Cedar also in place with marks. Corner was restored to perpetuate a government corner, and to control surveys in Section 3.

Corner was placed and witnessed May 25, 1959.

SURVEYORS SEAL

SIGNED Kenneth J. Ostling DATE 6/3/59  
REGISTERED LAND SURVEYOR