## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

т. 35\_\_\_\_ и.п. 4 в

|                        |             |           |         | Presq       | ie Isle |          | COUNTY      |
|------------------------|-------------|-----------|---------|-------------|---------|----------|-------------|
| DESCRIPTION OF CORNER  | 1/4 ω       | rner comm | on to   | Sections    | 2 and 3 |          |             |
| CORNER MONUMENT        | I" pipe     | with 4m   | brass ( | ар          |         |          | <del></del> |
| DATE MONUMENT PLACED A | MD WITHESSE | p Februa  | ry 22,  | 1961        |         |          |             |
| WITHESSES TO CORNER    |             |           |         | <del></del> |         | <u> </u> |             |
| N                      | 8#          | Balsam    |         | N75E        | -       | 13.7     | feet        |
| ž                      | 711         | Cedar     | -       | s4 <b>w</b> | -       | 38.7     | feet        |
|                        | AND         | J- 18     |         |             |         |          |             |

## DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement between section corners by Forestry Division survey crew while making a survey in this area. Found a squared, scribed post which checks exactly for latitude but fails 20 links east of true position. Nothing evident to support this location so concluded that post was erroneously placed, although intended to be on true line between section corners. Reset post at true corner, on line at proportionate distance between section corners.

SURYEYOR'S SEAL

SIGNED REGISTERES CAND SURVEYOR DATE 2-24-61