MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

т. <u>35</u> и.е. <u>4 г</u>

		Presque	COUNTY		
DESCRIPTION OF CORNER 1/4 corner con	mon to Sect	ions 2 a	nd 11		
CORNER MONUMENT IN pipe with 44 1	rass cap		_		
DATE MONUMENT PLACED AND WITHESSED Febr	wary 21, 1	961			
WITHESSES TO CORNER					
24" W. Pine	e stump -	87±₩	_	59.6	feet
6# Cedar		N7E	_	80.5	feet
AMD CIRCLE CORNER REGISTERED				~~	

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement between section corners, by Forestry Division survey crew while making a survey in this area. Corner falls in beaver flooding which has been inundated many times. Unable to identify original BTs.

SURVEYOR'S SEAL

SIGNED Cureth & Orling DATE 2-24-61