

JAN 17 1996

1995 PRESQUE ISLE COUNTY, STATE OF MICHIGAN REMONUMENTATION COMMISSION

2226

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 316 PAGE 309

For corners in PRESQUE ISLE (County)

Table with columns: Located In: (T 36N R 2E), Corner Code: # (I-3)

PRESQUE ISLE COUNTY RECORDED

95 OCT 20 PM 4:33

Janet M. Lamb REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

Grid table with columns A-M and rows 2-13, containing numbers 1-36 and a dot at row 3, column I.

I, Ronald Bischer, in a field survey on May 30, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:


NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- GLO Notes - 1856 Resurvey S47°E 16.80' 24" Cedar
Geo. H. Cannon S51°W 23.38' 12" Cedar
Set wood post N53°W 17.25' 9" Cedar
Tamarac 10" N26°E 18 1/2 lks
Tamarac 11" S16°W 38 lks
02-24-94 - Ronald R. Bischer same as 02-05-93
02-05-93 - Ronald R. Bischer
Found 1/2" Rod & Cap #15410 in 1" Pipe
N20°E 6.57' 6" Cedar

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- Found 1/2" Rod and Cap #15410 in 1" Pipe
N20°E 6.57' 6" Cedar
S47°E 16.80' 24" Cedar
S51°W 23.38' 12" Cedar
N53°W 17.25' 9" Cedar



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- 1/2" Rod and Cap #15410 in 1" pipe
N20°E 6.57' 6" Cedar
S47°E 16.80' 24" Cedar
S51°W 23.38' 12" Cedar
N53°W 17.25' 9" Cedar

Ratified by Peer Group in accordance with P.A. 345
Chairman [Signature]
Date 9/20/95

Nails with witness tag #22428 used.

Signed by Ronald R. Bischer Date Oct 3, 1995
Surveyor's Michigan License No. 22428