## SURVEY & REMONUMENTATION

OCT 0 5 1998

4588

4. Lot No. 5. Private Claims

## SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN ROSCONNON COUNTY

For comers in			KEUKUEU
Roscommon (County)	Located In:	Corner Code #	8 JUN 98 10:12 A.M.
Public Land Survey	T <u>22N R 1W</u> T R	<u>M-12</u>	ROBERT W. SHITH REGISTER OF DEEDS
	TR TR		
2. Property Controlling in Section	STR STR		FILE IN LIBER 3 OF LAND CORNER
3. Miscellaneous	STR STR		Register of Deeds Stamp & File Numb

I, Marvin E. Myers\_, in a field survey on 3-26, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO - 1837 John Brink, D.S.

Mon. - Post

11" Pitch Pine N81°30W 38 lks.

10" Yellow Pine \$43°W 56 Ks.

Marcus Schaaf, RLS (early 1900's) Found or established and replaced

George D. Henning, RLS #2240 May 1967 Mon - Computed position no monument set.

\_, Recorded Plat \_

**ROSCOMMON COUNTY** PEER GROUP APPROVAL DATE MAY 15th 1998

Many E. Myen MEN Marvin E. Myers, P.S. **County Surveyor** 

L. 3, Pg. 505 (Robert L. Higgins P.S. #21570 Sept. 24, 1982)

Mon. - Set 1/2" X 18" bar. Set single Proportionate between M-11 and M-13 of T22N-R1W (Based on unrecorded G. D. Henning survey). Spike in top of 15" Oak Stump N66°W 22.36"; 9" B. Oak N64°E 48.60"; 8" R. Oak S86°E 31.55"; 7" B. Oak S39°E 40.45"; CL of trail road East 8.0"; 1½" Pipe SE. 10.15"; 1/2"X18" Steel bar East 33.0"

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

POFESSION

Found 1/2" Iron and Cap #21570 @ witnesses from Robert Higgins survey. Could not find the 12" Pipe that was used as a witness in the Robert Higgins survey. This Pipe is believed to originate from Marcus Schaaf, from the early 1900's. Found pits & mounds, at N60°E, and S60°W, measuring 66' slope distance between the center of the pits. Set temporary nail at the midpoint and on line between the two pits. Distance to ½" iron bar matches call made by Robert Higgins Survey (L. 1, Pg. 306, 306), which states: Found 11/2" pipe SE 10.15'. Replaced temporary nail with Standard County Monument. Found square concrete Chunks in hole. Discussed the Higgins & Henning position at length, which was rejected in favor of the Schaaf Monument. Accepted as a perpetuation of the Original Government Corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon.- Standard Rescommon County Monument. Wit: 1/2" iron Bar & Cap NW 10.15; Found nall in N. side of 10" Oak N76°E 25.42; Set nail in N. side 8" Oak N77°W 61.96 Set nail in E. side 6" Oak clump N14°W 60.02; Set nail in SE side 16" B. Oak N30°E 62.28; Set Carsonite Post West 14±

MINISTER STREET OF MICHIQ MARVIN E. MYERS **PROFESSIONAL** Surveyor's Michigan License No. 31600 SURVEYOR No.

Date Juna, 5/1998