LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Roscommon (Gourly)		Located In:			Corner Code 111
1	Public Land Survey		T	R	
			T	R	
			Τ.,	R	
			T	R	
2.	Property Controlling	s	27 T 22N	R 3W	76-
	in Section	S	T	R	
3	Miscellaneous	s	T	R	
	Property in Sec	S	T	R	

Register of Deeds Stamp & File Number


, Recorded Plat 4. Lot No.

Private Claims

[Carl R. Johnson] in a field survey on re-set Nov. 4, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in tines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:



- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 7 Re-set corner at location previously established by K. J. Ostling RLS in 1981 set midway and on line between section corner to north and 4 corner south.

C Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" bar \sqrt{v} cap (originally set 1981) 1006**B** S38°E *Power pole 45.0 s65°W SW corner cement block bldg *20" Red Oak N25^OW *8" Jack Pine N47^OW 41.34' 35.14' *Witnesses: Nail & Ref. marker

Surveyor's Michigan License No.

Date 30083

LAND SURVINION LAND SURVEYORS