## SURVEY & REMONUMENTATION

APR 2 4 1995

ROSCOMMON COUNTY COMMISSION PEER GROUP APPROVAL

ROSCOMMON COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN ROSCOMHON COUNTY RECORDED

			MEM
or	corners	in	1.11 - 1

Roscommon

Property in Sec.

Private Claims \_

expressed below:

Located In: Corner Code ## (County) 1. Public Land Survey T 22N, R 4W \_\_ R \_ \_. R

16 DEC 94 2:39 P.M.

ROBERT W. SHITH REGISTER OF DEEDS

**Property Controlling** R in Section \_ T. Miscellaneous \_ R \_

. Recorded Plat

TO BE FILED IN LIBER 3 OF LAND CORNER!

Register of Deeds Stamp & File Number

Marvin E. Myers	_ , in a field survey on _	Dec 12,	19 <sup>94</sup>
do hereby certify that under in lines 1 and 2 above were current manual of survey ins	requirements of P.A. 74, Mic in conformance with regu	higan P.A. of 1970, the lations and rules the	e corner points mentioned erefore as required in the
Management or by a decree of above were in conformance.	of a Court of Law and/or tha	t the corner points me	entioned in lines 3, 4 and 5

12

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Court of Law; established, re-established, monumented, re-monumented, recovered, found as

A. Description of original monument and accessories and/or subsequent restoration:

G. Henning/R. Ostling 7-25-45 Mon- Found of iron bar in fence intersection G.Henning 2-11-47 WESTMORELAND SUB L.3, P18 Wit- None given
LCRC L.2, P262
Mon- ½" bar
Wit- None given

L. Cavanagh Sep 1990 Mon- Unknown Wit- not given

L. Cavanagh June 1994 Mon- Unknown Wit- None given

Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found concrete monument. Accepted as the best available evidence of the postion of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: Mon-Set Standard Roscommon County monument mark cap " 31600".

Wit- Found concrete monument N86°W 49.82

Set nail & tag E. side 28" Willow South 75.53 Set nail & tag NW side Utility Pole N45°E 5.19 Set nail & tag NW side 10" Tr. Elm N04°W 103.76 NW corner Concrete Block foundation S70°E 98.43 S03°58'40"W 2631.55 to J-5 N83°00'02"W 2644.59 to I-4



Surveyor's Michigan License No. \_

Date ...

Dec 15, 1994 = 45