

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 23 NR 2 W

Roscommon

COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 28 and 29

DESCRIPTION OF CORNER MONUMENT Left 1 1/4" pipe in place

WITNESSES TO CORNER

6" Balsam - S62W - 23 1/2 links

7" Balsam - S18E - 42 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a survey in this township. Found 1 1/4" pipe at corner, previously restored from the Government BTs by Marcus Scheaf, Reg. Land Surveyor. SW 1/4 Pine BT stump in place with good face, and remains at site of Hemlock east.

Corner was witnessed Aug 19, 1959.

SURVEYORS SEAL

SIGNED *Levith J. Oetting*
REGISTERED LAND SURVEYOR

DATE 8/28/59