

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 23. NR. 2. #

Roscommon

COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 34 and 35

DESCRIPTION OF CORNER MONUMENT Left 1 1/2" pipe in place

WITNESSES TO CORNER

7" R. Pine	-	S56E	-	35 1/2 links
12" W. Pine	-	S27.1	-	48 1/2 links
4" Conc. Monument	-	S85W	-	51 1/2 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division land surveyor while looking for corners in this township. Found 1 1/2" pipe in place, in small swale. N. BT stump in place with good face, and site for SE BT. Corner was witnessed to perpetuate a good corner.

Corner was witnessed December 1, 1959.

SURVEYORS SEAL

SIGNED Kenneth J. Ostling
REGISTERED LAND SURVEYOR

DATE 12/14/59