MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T 23 NR 2 W

	Roscommon COUNTY
DESCRIPTION OF CORNER	1/4 corner common to Sections 19 and 20
DESCRIPTION OF CORNER	MONUMENT_in pipe with in brass cap
WITNESSES TO CORNER	
	19" R. Oak - N38 - 74 links
	No other near

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division surveyor while making a survey in this area. Found 11 pipe in place, as previously restored by Marcus Schaaf, Registered Land Surveyor, from remains of the government BTs. Corner was restored to perpetuate a good corner.

Corner was placed and witnessed September, 1954.

SURVEYORS SEAL

SIGNED SUPPLY DATE 12/14/59