## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T 23 NR 2 #

	-		OBCOMMO	<u>.                                      </u>	COUNTY
DESCRIPTION OF CORNER	Section corne	er commo	on to Sec	ctions	19-20-29-30
DESCRIPTION OF CORNER	MONUMENT1	pipe_w	with 4"	brass	cap
WITNESSES TO CORNER					
	18" R. Pine	<del>-</del>	N33W		75 links
	14" W. Oak	-	sse	-	56½ links
			<b></b>		<del></del>

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by For estry Division surveyor white making a survey in this township. Found line pipe in place, previously restored by Markus Schaaf, Reg. Land Surveyor, from remains of original BTs.

Corner was placed and witnessed September, 1954.

SURVEYORS SEAL

SIGNED CENTER DATE 12/14/59