

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 23.. NR. 2 W. ....

Roscommon

COUNTY

DESCRIPTION OF CORNER  $1/4$  corner common to Sections 2 and 11

DESCRIPTION OF CORNER MONUMENT Left  $1\frac{1}{2}$ " pipe in place, 18" above ground

WITNESSES TO CORNER

12" J. Pine - N1W -  $126\frac{1}{2}$  links

14" W. Pine stump - S16W -  $8\frac{1}{2}$  links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division Land Surveyor while searching for corners in this township. Corner was previously restored by Marcus Schaaf, RLS, from evidence of the original Bts. Both stump bottoms still in place but badly burned, and cannot identify markings. Our SW NBT was previously scribed  $1/4$ .

Corner was witnessed October 4, 1960.

SURVEYORS SEAL

SIGNED

*Kenneth J. Ostling*  
REGISTERED LAND SURVEYOR

DATE 10/10/60