

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 23. NR. 2 W. . . .

Roscommon

COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 1-2-11-12

DESCRIPTION OF CORNER MONUMENT Left 1 1/4" pipe in place, 2' above ground

WITNESSES TO CORNER

7" J. Pine	-	N37E	-	41 links
10" J. Pine	-	West	-	78 1/2 links
7" Spruce	-	S30E	-	24 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division Land Surveyor while searching for corners in this township. Found 1 1/4" pipe in place, as previously established by Marcus Schaaf, RLS, from remains of SE gov't BT, which is now badly rotted. Corner checks good with swamp edge west.

Corner was witnessed October 4, 1960.

SURVEYORS SEAL

SIGNED *Kenneth J. Ostberg*  
REGISTERED LAND SURVEYOR

DATE 10/10/60