4626

For corners in
Roscommon County

	Located in:	Corner Code #
1. Public Land Survey	T23N R 2W	J-1
	T24N R2W	J-13
	T___ R___	_____
	T___ R___	_____

Register of Deeds Stamp & File Number

I, Larry L. Cavanagh, in a field survey June 20, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in line 1 above was in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

A. Description of original monument and accessories and/or subsequent restoration:

    SET POST BY WILLIAM BURT, 1852
    WIT: TAMARACK 12 N70E 18
         TAMARACK 10 N54W 29

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

    NO ORIGINAL EVIDENCE FOUND. THIS CORNER WAS RE-ESTABLISHED BY SINGLE PROPORTIONATE DISTANCE
    BETWEEN I-1 AND L-1.
    J-1 TO I-1 S89°02'47"W 2644.43'
    J-1 TO L-1 N89°02'47"E 5288.87'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

    SET 3/4" X 5' BLACK IRON PIPE & CAP 17614 (IN SWAMP)
    NAIL & TAG IN 3" MAPLE S50°E 4.25'
    NAIL & TAG IN 3" SPRUCE N14°W 32.67'
    NAIL & TAG IN 18" W. PINE N1°E 29.84'
    CARSONITE POST WEST 1.53'

A CAREFUL AND FAITHFUL ESTABLISHMENT OF THE POSITION OF THE CORNER.

SURVEY &
REMONUMENTATION

APR 0 7 1998

SECTION

ROSCOMMON COUNTY
PEER GROUP APPROVAL
DATE July 8, 1997

Marvin E. Myers, P.S.
County Surveyor

Signed by _____   Date July 9, 1997
Surveyor's Michigan License NO. 17614

LIBER 3 PAGE 419