LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Roscommon	Located in:	Comer Code #	
(County)			
			PTATE OF WARRANT
Public Land Survey	T <u>23N</u> R <u>3W</u>	<u>(M-8</u>)✓	STATE OF MICHIGAN
	т <u>23N</u> в <u>2W</u>	A-8	ROSCONNON COUNTY
	T R T R		RECORDED
0. Description 0. 1. 10	_ T R		26 SEP 96 3:37 P.H.
	ST_R		70 OF 16 2011 L'U.
in Section 5	S T R		RORERT II CHITU
3. Miscellaneous Property in Section	ST R ST R		TO BE FILED IN THER 3 OF LAND CORNERS
Property in Section 3	э і н		Register of Deeds Stamp & File Number
4. Lot No, Reco	rded Blot		
5. Private Claims	rucu i iai	· · · · · · · · · · · · · · · · · · ·	A B C D E F G H I J K L M
. , , , , , , , , , , , , , , , , , , ,			2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Larry L. Cavanagh, in a	a field survey on AUC	ust 10 96	10 11 12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned			
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current			
manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and			
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a			
Decree of a Court of Law; establish	ed, re-established, monument	ed, re-monumented, recovered	found 9
as expressed below:			10 30 29 28 27 28 25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded			
on this certificate.			12 31 32 33 34 35 36
A. Description of original mor	Niment and accessories a	od/or subsequent	13
The second secon	iument and accessories at	ravor subsequent restoration	in:
GLO - John Brink - 1836	C. Johnson 1-28-92	LCRC MSHD C	Lindgren (1994 f. notes)
mon set post	mon fd. 1 1/4" pipe		• •
wit hemlock 18" S55 1/2W 21 lks	bar L1, pg 306		W 38.72'-14" oak (DNR)
beech 8" N43W 9 lks	wit 8" r. oak N78°\		W 44.90' -12" oak (DNR)
G. Henning 1955 sec survey	6" r. oak S82°V 8" ironwood N7	•	E 51.41' -12" elm (DNR) W 71.44' -12" Birch
shows no mon on map	10" maple \$27°		W /1.44 -12 Birch
-	nail w/ref. tags		
	I 1/4" pipe \$72°	W 33.55'	
B. Description of corner evide			
B. Description of corner evide	ance round and/or method	applied in restoring or rees	stablishing comer:
fd. 3/8" re-rod			
wit fd. nails w/tag (DNR)	•	ROSCOMMON COUN	TY
14" oak N75°W 38.72'			
12" oak S85°W 44.90'		PEER GROUP APPRO	
12" elm N70°E 51.47"		DATE Style 19	C. Aller,
		DATE Les 16, 199 Opener E. Thys	
		All - Holes	
Marvin E. Wyers, P.S.			
County Surveyor			
C. Description of monument t	or comer and accessories	established to perpetuate	locating the position of the corner:
The best available evidence of the pos	ition of the Original Corner.		
monument set standard Roscommon (06 17614 in north have 1130 as a few	at attack
wit - Fd nail & tag 12" elm N67°E 51		20-17014 in part box 1 West of ce	nierine
Fd nail & tag 14" r. oak N81°W			WHATE OF MICE
Fd Nail & tag 12" r. oak S85°W			HANGE ATE OF MICHIEL
set nail & wit tag 22" maple N30 carsonite post 37.0' East	°E 66.94'		F# IADOV. VI
omborate post 57.0 East			LARRY L * T
Λ			FRONTESIALLA S. F
SURVEYOR OF			
7 17614			
Signed by // yearn	- cercy	Date	9-16-96 17614
Surveyor's Michigan License No. 17614			
REVISED MAY 14, 1975			
·			REVISED JAN., 1963

LIBER 3 PAGE 322