

APR 24 1995

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
ROSCOMMON COUNTY
RECORDED

For corners in

COMMISSION

10 NOV 94 3:28 P.M.

Roscommon (County)	Located In:	Corner Code #
1. Public Land Survey	T 23N R 4W	E - 10
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____	Recorded Plat _____	
5. Private Claims _____		

ROBERT W. SMITH
REGISTER OF DEEDS

ROSCOMMON COUNTY

PEER GROUP APPROVAL MEM

DATE 9-15-94

Register of Deeds Stamp & File Number

I, Marvin E. Myers, in a field survey on September 8, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:


GLO-Artemas Curtis 1852
Mon-Set Post
WIT: 2 1/2" Tamarack N75°W 107 lks.
2 1/2" Tamarack S65°E 140 lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found no evidence of monument or accessories. Re-established by single proportionate measure positioned between E-9 and E-11.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon-Set 3/4" I.D. x 48" galvanized iron pipe & Cap stamped "MEM 31600" in backslope of East ditch of abandoned road grade
WIT: Set Carsonite Post South 3.00'
E-9 N00°57'53"E 2595.86'
E-11 S00°57'53"W 2595.86'
Set nail 10'± W. of W. edge asphalt in shoulder of S. Bnd. US 27 N76°13'39"E 1521.36'
Set nail in ground at intersection of N-S & E-W abandoned roads S02°00'05"W 630.28'
Set nail in ground S. edge of marsh N00°14'05"E 1088.97'



Signed by Marvin E. Myers
Surveyor's Michigan License No. 31600

Date October 11, 1994