SURVEY & REMONUMENTATION

9562

as expressed below:

on this certificate.

MAY 28 1997

STATE OF MICHIGAN LAND CORNER RECORDATION CERTIFICATE ROSCOMMON COUNTY Filing Requirement of Act 74, Mich. P.A. 1970 RECORDED For corners in Roscommon Located In: Corner Code # 23 DEC 96 9:49 A.M. ROBERT W. SMITH T 24N, R 3W 1. Public Land Survey REGISTER OF DEEDS _T _ 2. Property Controlling ___T ____R_ in Section __ T 3. Miscellaneous Register of Deeds Stamp & File Number Property in Section __, Recorded Plat_ 4. Lot No. 5. Private Claims _ I, Marvin E. Myers , in a field survey on December 6, , 1996 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

placed post

Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found

Description of original monument and accessories and/or subsequent restoration: GLO William Burt 1852 SOVEREIGN PARK 1903 A.E. Newman R.T. Ostling (no Date) Not Set. Mon- Heavy Cedar Post Mon-1½ pipe L.2, P.208. Summer 1943 G.D. Henning & RTO L.306, P.82 R.L. Higgins Mon- I" Pipe Mon-Pipe (Believed to be set Mon- Fd l" Pipe G.D.Henning 1942 by A.E. Newman) Wit- $\frac{1}{2}$ " Bar N5°45'E 103.05 Mon- Pipe July 1924 G.F.Delamater Et Cor. S88°30'E 2646.60 Mon- Gas Pipe said to be in G.D. Henning 1944 position where Newman had Mon- Pipe

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found $1\frac{1}{4}$ x 21" long pipe, found $\frac{1}{2}$ " bar North 103.05, found $\frac{1}{2}$ " bar with red painted top East 70.0 Measured N86°02'07"E 2645.74 to E-2; Measured S86°16'22"W 2445.67 to C-2; Measured N00°18'53"E 3730.02 to D-1. This position was not established by original government survey. The $1\frac{1}{4}$ pipe is reported in previous surveys of record as having been set by A.E.Newman. This position not at the theoretical position, however this position has been used for 93 years, and is accepted as the best available evidence of the position of the corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner. Replaced 12x21" pipe with standard Roscommon County monument. Wit - 6" W. Pine N77°E 19.85

12" Clump of Maples N40°W 9.31

30" W. Oak S6°W 44.67

4" W. Pine S43°E 10.93

ROSCOMMON COUNTY PEER GROUP APPROVAL

DATE 2011, 1996

Marvin E. Myers P.S. Surveyor's Michigan License No.

Dec 21, 1996 Date

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 **REVISED MAY 14, 1975** SEVISED JAN. 1983

11BED 3 PAGE 362