MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_24_ NR_4_ W__

			ReasonmenCOUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between Sections 29 & 30
DESCRIPTION	OF	CORNER	MONUMENT_1º Pipe with 4º Brase cap
WIT TNESSES	то	CORNER	12" Cedar - # 3 F - 16 Links
			_ 8* Spruge = H 23 W 19 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established, by proportionate measurement, by Forestry Division survey crew, while making a partial resurvey of this Township.

Corner was placed and witnessed March 17, 1952.

SURVEYORS SEAL

SIGNED SEM C. SEL DETW DATE 4/15/52
REGISTERED LAND SURVEYOR