Property in Sec.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF HICHIGAN RUSCONNEX COUNTY RECORDER

For corners in 8 JUN 99 3:50 P.M. Corner Code # Located in: Roscommon ROBERT W. SMITH REGISTER OF DEFIS T 24N R 4W 1. Public Land Survey 2. Property Controlling S R in Section S FILE IN LIBER 3 OF LAND CORNERS 3. Miscellaneous R S

, Recorded Plat 4 Lot No 5. Private Claims

I, Marvin E. Myers, in a field survey on April, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1			c .) E	F	. (}	i i		ı k	(L	. N
	•	P -										
2	Г	ь — !	Γ)		_	—	i	2	. —		-
3		1-	-									
4	-	i –	-	ġ	9		1	Ò	1	1-	1	2
5		1	-	ļ.,					_			
6	<u></u>	8	↩	ا 7	1	6—	1	5	1	4—	—1	3—
7		_	_	L_								
В	L,	 9	L,	0-		4) 		2		4
		-	T '	Ĭ		,		ĺ		3 		4
9												
10	—	90 —	1-2	9 —	 2	8—	—2	7-	<u> </u>	6—	— ₂	5
11	-	-	1	\vdash				-				
12		31	╁	32	<u> </u>	3—	—3	4—	<u> </u>	5—	<u> </u>	6—
13	L.,	<u> </u>	L		L						Ш	

Register of Deeds Stamp & File Number

Description of original monument and accessories and/or subsequent restoration:

G.L.O - 1839 John Brink, D.S.

Marcus Schaaf 1940's Mon - Iron Set

Mon -- Post

Wit: 10' W Oak N56°F 46 lks

11" Yellow Pine N48°W 35 lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Schaaf 1 1/2" pipe in concrete. Accepted pipe as the best available evidence of the position of the Original Corner. Replaced pipe with Standard Crawford County Monument.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon: Standard Crawford County Monument.

West edge of Carsonite Post N52°E 19.50

Nail & tag SE side 4" Maple N61°E 20.27

Nail & tag SW side 5" W. Pine S28°E 48.65

Nail & tag SW side 4" Maple (clump) N46°W 20.36

MAR 01 2000

SECTION

RUSCOMMON COUNTY

PEER GROUP APPROVAL

Marvin E. Myers, P.S. **County Surveyor**

WHITHING . ATE OF MICH MARVIN E. **MYERS PROFESSIONAL** SURVEYOR No. 31600 POFESSIONA

Surveyor's Michigan License No. 31600

LIBER 3 PAGE 601