## LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN Filing Requirement of Act 74, Mich. P.A. 1970 ROSCOMMON COUNTY For corners in RECORDED Comer Code # Located in: Roscommon 28 APR 99 11:48 A.H. (County) T 22NR 4W J-10 1. Public Land Survey ROBERT W. SMITH R REGISTER OF DEEDS R R 2. Property Controlling S T FILE IN LIBER 3 OF LAND CORNERS Т R in Section Ŧ Register of Deeds Stamp & File Number 3. Miscellaneous Property in Sec. , Recorded Plat 4. Lot No. 5. Private Claims \_ I, Marvin E. Myers , in a field survey on November 24, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: **ੴ** Not more than 2 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: L2, P277 LCRC LCRC L. 1, P. 83-84 April 1973 L. L. Cavanagh, P.S. #17614 Mon - 1⁄2" Bar Wit: 10" Oak \$60°E 47.75 Mon - Found 1/2 " Bar 4" Oak N85°W 22.15 Wit: 10" Oak S60°E 47.75 8" Oak North 47.9 4" Oak N85°W 22.15 8" Oak North 47.9 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found  $\frac{1}{2}$ "x 18" bar at intersection of  $\frac{1}{4}$  lines. 1 foot south of fence post. Accepted  $\frac{1}{2}$ " bar as a careful and faithful establishment of the position of the corner. Replaced 1/2" bar with Standard Roscommon County Monument. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Mon - Standard Roscommon County Monument. Wit: Set spike in 10" Blazed Oak N25°W 27.49 Set spike East side 4" Poplar S21°W 26.93 MINIME. Set spike in North side 6" Maple N64°E 24.13 Set spike in South side 10" Poplar N79°W 8.84 MARVIN E. MYERS DESSIONA **RUSCOMMON COUNTY BURVEYOR** 

Signed by Surveyor's Michigan License No. 31600

Marvin E. Myers, P.S.

PEER GROUP APPROVAL

DATE ADRIL 19, 1999

**County Surveyor** 

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 HEVISED JAN., 1983 REVISED OCT., 1995

81600

OFESSIONA